



# Wire, rod, and pipe drawing

# Overview

## **Wire/rod drawing**

application

deformations, drawing speeds and forces

equipments, dies and die materials

## **Tube drawing**

tube drawing processes


strain and drawing force

drawing tools

## **Lubrication**

## **Defects**

# Wire drawing



A wire of a larger size is pulled through a drawing ring of a smaller size.

- coarse drawing:  $d = 16$  to  $4.2$  mm
- medium drawing:  $d = 4.2$  to  $1.6$  mm
- fine drawing:  $d = 1.6$  to  $0.7$  mm
- ultra-fine drawing:  $d < 0.7$  mm

According to the machine used (continuous operation):

- single-draft drawing
- tandem drawing

The machines are operating continuously.

# Stock, application

**Starting stock** wire drawing: hot-rolled wires

rod drawing: rods produced by hot rolling or extrusion

## Application

wires and rods with smooth surfaces and low tolerances.

Material	Application
Low-carbon steels C 10 – C22	Wires, wire meshes, barbed wire, pins, nails, screws and bolts, rivets
High-carbon steels (up to 1.6% C)	Rod material for automatic processing, wire cables
Alloyed steels	Industrial springs, welding wires
Cu and Cu alloys	Wires, wire meshes, screws, bolts and shaped parts, parts for the electrical industry
Al and Al alloys	Screws and bolts, shaped parts, electrical lines, etc.

# Deformations

**Strain**

$$\varphi = \ln \frac{A_0}{A_1}$$

$A_0$  : cross-section before drawing

$A_1$  : cross-section after drawing

## Permissible deformations

Material	Intake strength $R_m$	Intake diameter $d_0$	Drawing reduction between two draws, $\varphi$	Total deformation $\varphi$	Number of drawing stations
Steel wire	400	4 – 12	0.18 – 0.22	3.80 – 4.00	8 to 21
	1200	0.5 – 2.5	0.12 – 0.15	1.20 – 1.50	
Cu alloy	soft	8 – 10	0.40 – 0.50	3.50 – 4.00	5 to 13
	250	1 – 3.5	0.18 – 0.20	2.00 – 3.00	
Al alloy	soft	12 – 16	0.20 – 0.25	2.50 – 3.00	5 to 13
	80	1 – 3.5	0.15 – 0.20	1.50 – 2.00	

# Deformations

Reductions of higher than 45% may result in lubricant breakdown, leading to surface-finish deterioration.

## ***Sizing pass:***

Light reduction to improve surface finish and dimensional accuracy. It basically deforms only the surface layers, so it produces highly non-uniform deformation of the material and its microstructure. The properties of the material will vary with location within the cross section.

## ***Bundle Drawing:***

Drawing many wires (hundred or more) simultaneously as a bundle. The cross section is polygonal, rather than round.

# Drawing force



$$F = A_1 \sigma_{f \text{ mean}} \varphi \left( \frac{\mu}{\alpha} + \frac{2\alpha}{3\varphi} + 1 \right)$$

$F$  drawing force

$\sigma_{f \text{ mean}}$  mean flow stress

$\mu$  friction coefficient

$2\alpha$  cone angle (radian)



Optimal drawing angle:  $2\alpha \approx 16^\circ$

# Drawing speeds

## Single


Material	Intake strength $R_m$ in N/mm <sup>2</sup>	$v_{\max}$ in m/s
Steel wire	(iron wire) 400	20
	800	15
	1300	10
Cu (soft)	250	20
Brass, bronze	400	
Al and Al alloys	80 – 100	25

## Tandem


Drawing speed differs at every drawing stage. As the volume is constant, the speed is getting higher because the wire cross-section is reduced.



# Drawing equipment



single



tandem

# Drawing tools

## Three zones:


- cone-shaped intake (entry angle  $2\beta$  and approach angle  $2\alpha$ )
- bearing land
- cone-shaped back relief (relief angle  $2\gamma$ )

The length of the cylindrical guiding land:

$$l_3 = 0.15 \cdot d_1$$

The approach angle  $2\alpha$  influences the drawing force and the surface finish of the wire (ref.: optimal angle).

There are dies for profile drawing as well.




# Drawing die materials

## Steel drawing dies


Material	HRC working hardness	Fields of application
1.2203 1.2453 1.2080 1.2436	63 – 67	Rod and tube drawing

## Carbide drawing dies (Typical designs)


Cylindrical casing



Conical casing




Enlarged die




# Drawing die materials

## Diamond drawing dies

For drawing fine and ultra-fine wires (1.5 mm to 0.01 mm) made of copper, steel, tungsten and molybdenum.



The diamond is sintered into a steel casing.




# Tube drawing

*Drawing of hollow parts, where the outside is formed by a drawing die hole and the inside by a plug or a rod.*

## **Tube drawing processes**

*Drawing without a mandrel (tube sinking)*

- no support from inside
- only the external diameter's tolerance is good
- only applied to tubes with smaller internal diameters




1 Drawing die, 2 workpiece




# Tube drawing

*Drawing over a stationary mandrel (plug)*



1 drawing ring, 2 workpiece, 3 mandrel, 4 plug

*Drawing over a floating plug*




1 drawing ring, 2 workpiece, 3 floating plug

# Tube drawing

## *Drawing over a moving mandrel*

The rod and the tube are simultaneously moving in the drawing direction.



1 Drawing ring, 2 workpiece, 3 moving mandrel


# Strain and drawing force

## Limit

The limit for the deformation comes from the required drawing force.

$$F_{drawing} < F_{perm.}$$

$$F_{perm.} = A_1 \sigma_{flow 1}$$



$$F_{drawing} = \frac{A_1 \sigma_{flow mean} \varphi}{\eta}$$

$$\eta = 0.4 - 0.6 \quad \text{for} \quad \varphi = 0.15$$

$$\eta = 0.7 - 0.8 \quad \text{for} \quad \varphi = 0.50$$




# Strain and drawing force

Type of drawing	Permissible deformation, cross area in % (from drawing force)	Principal strain $\varphi_p$ (–)
Tube sinking	20 – 50	$\varphi_p = \ln \frac{d_0}{d_1}$ $\varphi_{p\%} = \varphi_p \cdot 100 (\%)$
Plug drawing	30 – 50	$\varphi_p = \ln \frac{A_0}{A_1}$ $\varphi_p = \ln \frac{D_0^2 - d_0^2}{D_1^2 - d_1^2}$
Rod drawing	40 – 60	$\varphi_{p(\%)} = \varphi_p \cdot 100 (\%)$

# Drawing tools

Steel body drawing mandrel with carbide tool:



Drawing mandrel with screwed-on carbide ring

# Lubrication - wire and tube drawing

**Tube drawing:** difficulty of maintaining a sufficiently thick lubricant film inside, at the *mandrel-tube interface*.

**Drawing of rods:** a common method is phosphate coating.

## Lubricating regimes

**Wet drawing**, in which the dies and the rod are immersed completely in the lubricant.

**Dry drawing**, in which the surface of the rod to be drawn is coated with a lubricant by passing it through a box filled with the applied lubricant (stuffing box).

**Metal coating**, in which the rod or wire is coated with a soft metal, such as copper or tin, which acts as a solid lubricant.

**Ultrasonic vibration** of the dies and mandrels; in this process, vibrations reduce forces, improve surface finish and die life and allow larger reductions per pass without failure.

# Defects - wire and tube drawing

## **Cold forming - residual stresses**

*stress-corrosion cracking*

*warp*                      *deformation if a layer of material subsequently is removed (machining, or grinding)*

## **Rod and wire**

*center cracking*                      *(similar to those in extrusion)*

*seams*                      *longitudinal scratches or folds  
(seams may open up during subsequent forming operations)*

*die marks*

# Flow through conical dies - Summary

## **Three techniques use conical die**

*extrusion, drawing (wire & rod) and reduction.*

## **The common basics may lead to one of the three, depending on the border conditions**

*Zero/small axial stress at ingoing → wire / rod drawing*

*Zero axial stress at outgoing → extrusion*

*Smaller than flow stress at ingoing → reduction*

# Wire, rod and tube drawing

**Thank you for your attention!**